

MAX ARTUS TORRIS COIN LED

οδηγίες τοποθέτησης

εσωτερικού χώρου / χωνευτά οροφής





1




Εγκατάσταση


Ανοίξτε οπή στην ψευδοροφή.









Απασφαλίστε το εσωτερικό μέρος. Περιστρέψτε το μέχρι τις εγκοπές.




2 Τοποθετήστε το σώμα του φωτιστικού στην οροφή.




3 Στερεώστε το φωτιστικό στην οροφή με δύο (2) βίδες. Κρατάτε το φωτιστικό όσο χρησιμοποιείτε το δράπανο.




Εργαλεία / εξαρτήματα




4 Μετά την τοποθέτηση γεμίστε τα κενά της οροφής.



5 Έπειτα βάψτε την οροφή.



6 Τοποθετήστε τον λαμπτήρα στο φωτιστικό και στερεώστε τον με το ελατήριο (A). Κάντε τις συνδέσεις (B). Τοποθετήστε το εσωτερικό μέρος και περιστρέψτε μέχρι τις εγκοπές (Γ).



ΟΔΗΓΙΕΣ ΕΓΚΑΤΑΣΤΑΣΗΣ

- Η εγκατάσταση πρέπει να γίνεται από αδειούχο ηλεκτρολόγο.
- Εφόσον υπάρχει ακροδέκτης γείωσης, συνδέστε τον στη γείωση της εγκατάστασης.
- Βεβαιωθείτε ότι η παροχή είναι απενεργοποιημένη κατά τη συντήρηση.
- Η ισχύς των λαμπτήρων δεν πρέπει να υπερβαίνει την ένδειξη στο φωτιστικό ή στη συσκευασία.
- Μετά την εγκατάσταση ελέγξτε τη στερέωση και τη σύσφιξη των στυπιοθλιπτών, όπου υπάρχουν.
- Ο κατασκευαστής δεν ευθύνεται για τραυματισμούς ή ζημιές από λανθασμένη εγκατάσταση ή χρήση.
- Δεν προορίζεται για βρογχοειδή σύνδεση.
- Τα ούπα και οι κλέμες δεν περιλαμβάνονται.
- Τα στοιχεία LED αντικαθίστανται μόνο από τον κατασκευαστή.

ΠΡΟΣΟΧΗ

Φοράτε αντιστατικά γάντια όταν αγγίζετε τα LED.



BRIGHT ΕΙΔΙΚΟΣ ΦΩΤΙΣΜΟΣ

Εργοστάσιο

Κεφαλοβρύσου 5, Μονομάτι, Αχαρνές, Τ.Κ. 13677, Αθήνα, Ελλάδα Τηλ: (+30) 210 6208 230 |
E-mail: info@bright.gr | www.bright.gr


GREENLIGHT

MAX ARTUS TORRIS COIN LED


JUN 2025

installation instructions


indoor / downlights




1




Installation
Cut false ceiling.







Release the inner component. Turn it until you reach the gaps.




2 Fit the body of the luminaire in the ceiling.




3 Secure the fitting on ceiling with two (2) screws. Hold the fixture while using the drill.




Tool accessories




4 After installing the fitting, fill the gaps on ceiling.



5 Then, paint the ceiling.



6 Fit the lamp inside the luminaire and secure with the spring (A). Make wiring connections (B). Fit the inner component to the fixture and turn it until you reach the gaps (C).



7

USER INSTRUCTIONS

- The installation of the unit must be done by a qualified electrician.
- The unit must be earthed in case an earth connecting point exists.
- Ensure that the mains is switched off during servicing.
- Do not use bulb(s) bigger than the indicated on units name-plate or packaging.
- Ensure that after the installation, the unit is properly fixed and the cable clamps (if exist) are well tightened.
- Manufacturer will not accept liability for injury or damage resulting from incorrect use or installation
- The unit is not intended to operate in loop connection.
- Wall plugs and terminals are not included.
- LED modules are replaced only by the manufacturer.

CAUTION
Wear anti-static gloves
before you touch LED systems



BRIGHT SPECIAL LIGHTING

Factory
5 Kefalovrisou Str., Monomati, Acharnai, P.O. Box 13677, Athens, Greece
Tel: (+30) 210 6208 230 | E-mail: info@bright.gr | www.bright.gr

GREENLIGHT